
11HF CLAREMONT PARK BOSTON, MA 02118

AUGUST 12, 2019







EMBARC



SITE PLAN





EMBARC

SITE LOCATION

11HF CLAREMONT PARK BOSTON, MA 02118 REVISED AUGUST 23, 2019 AUGUST 12, 2019








SITE CONTEXT (CLAREMONT PARK)

copyright: EMBARC Studio, LLC. | C:\Users\mvanbrocklin\Documents\19023_11.5 Claremont_mvanbrocklin@embarcstudio.com.rvt



2



- REPAIR AND RESTORE EXISTING ROOF, AS REQUIRED.

- REPLACE EXISTING WINDOWS WITH PELLA ARCHITECT SERIES '1-OVER-1' WOOD WINDOWS.
- REPAIR AND RESTORE EXISTING ORNAMENT AND DOOR SURROUND, AS REQUIRED.
- RELOCATE EXISTING INTERIOR VESTIBULE DOUBLE DOORS TO EXTERIOR. REPAIR AS REQUIRED. REFINISH AND STAIN.


- NEW FRONT DOOR AND HARDWARE. SEE PAGE 5.
- REPLACE EXISTING GARDEN RAILING WITH NEW BLACK METAL RAILING TO COMPLEMENT NEIGHBORING RAILS. SEE PAGE 4.
- REPAIR AND RESTORE EXISTING FRONT STOOP, AS REQUIRED.



3



GARDEN RAIL AT 15 CLAREMONT PARK



PROPOSED FRONT RAIL



PROPOSED FRONT RAIL

copyright: EMBARC Studio, LLC. | C:\Users\mvanbrocklin\Documents\19023_11.5 Claremont_mvanbrocklin@embarcstudio.com.rvt

4



EXISTING DOOR HARDWARE




PROPOSED DOOR HARDWARE



PROPOSED HARDWARE: 'BALDWIN HARDWARE - MINNEAPOLIS ESTATE HANDLESET IN NON-LACQUERED

5



SITE CONTEXT (PUBLIC ALLEY)

11HF CLAREMONT PARK WITH REAR CHIMNEY VIEW










6




- ----- NEW ROOF DECK WITH BLACK METAL RAIL.
- ----- REPLACE EXISTING COPPER GUTTER, AS REQUIRED.
- REPAIR AND REPOINT EXISTING BRICK MASONRY FACADE, AS REQUIRED.
 FIXED PANELS.
- ----- REPLACE AND MOVE EXISTING COPPER DOWNSPOUT.
- REPLACE EXISTING WINDOWS WITH ALUMINUM-CLAD PELLA ARCHITECT SERIES '1-OVER-1' WOOD WINDOWS. PAINT BLACK.
- MODIFY FIRE BALCONY AS REQUIRED.
 REPAIR AS NEEDED AND REPAINT.
- NEW DECK WITH IPE DECKING AND BLACK METAL RAIL.
- NEW ALUMINUM-CLAD WOOD TRANSOM IN EXISTING OPENING.
- EXTEND NEW ALUMINUM-CLAD STOREFRONT IN EXISTING MASONRY OPENING TO GARDEN LEVEL.
- —— NEW 6'-0" CEDAR FENCE WITH HORIZONTAL BOARDS.
- ----- 8" CMU RETAINING WALL WITH CEDAR CLADDING.

11HF CLAREMONT PARK BOSTON, MA 02118 AUGUST 12, 2019

7








EMBARC

ROOF CONDITIONS

copyright: EMBARC Studio, LLC. C:\Users\mvanbrocklin\Documents\19023_11.5 Claremont_mvanbrocklin@embarcstudio.com.rvt

8



EXISTING DOOR AT 11HF CLAREMONT PARK



PROPOSED DOORS FOR 11HF CLAREMONT PARK (ONE OF PAIR SHOWN) (RE-USED FROM INNER VESTIBULE)

EMBARC

PROPOSED FRONT DOOR



9