


# 71 Beacon Street, Unit 5



**Proposed Work: Replace five fourth story, front/rear/side façade, six-over-six, true-divided light windows in-kind**



## Lead Safe Homes

[New Search](#) [Search Results](#)

Search Criteria:

Town: BOSTON  
StreetName: Beacon St  
Street Number: 71

### List of Details

Town	Address	Unit	Inspection Date	Inspection Type	Outcome	Inspected By	Inspector Licence#
BOSTON	71 Beacon St	5	6/21/2018	Comprehensive Initial Inspection	<a href="#">Hazards Found</a>	Benjamin Misch	3984

LeadSafeHomes - Hazards Found - Google Chrome

eoohs.ehs.state.ma.us/leadsafehomes/Violations.htm

### Hazards Found

At the time of inspection there were lead hazard found on the property. The inspection showed areas that did not meet Massachusetts rules for lead safety. Lead paint was found in poor condition (chipping or peeling), or on areas of windows that could make dust, or in areas where young children could reach it.

Under Massachusetts rules, these areas must be deleaded if there are children under 6 years old living there.



**Street View at Corner of Beacon St. and River St.**



**Street View of 71 Beacon St.**



**Close-up of Windows 3-5 on Beacon St.**



**Street View at Corner of River St. and Byron St.**



**Street View on Byron St.**



**Close-up of Window 1 on Byron St.**



**View on Byron Street, next to Private Garden (Window 2 not visible)**



**Close-up of Window 2 from Private Garden**



**Window 3**



**Window 3**





**Window 3**



**Window 4**



**Window 4**



**Window 4**



**Window 5**



**Window 5**



**Window 1**



**Window 1**



**Window 1**





**Window 2**




**Window 2**


JB PROPER BOSTONIAN SH WINDOW UNIT




T.D.L. BAR  
FULL SCALE



JAMB SECTION



HEAD SECTION



SILL SECTION