PROJECT:

CURLEY HOUSE EXTERIOR RESTORATION

350 JAMAICAWAY JAMAICA PLAIN, MA



CLIENT:

CITY OF BOSTON

1 CITY HALL SQUARE BOSTON, MA


ARCHITECT:



PRESIDENTS PLACE, 1250 HANCOCK STREET, SUITE 815N QUINCY, MA 02169 TEL. 617-773-8150 FAX 617-773-4902 www.wesslingarchitects.com

SHEET NUMBER	DRAWING TITLE	ISSUED FOR BLC - 02/01/21			DRAWING & SKETCHES ISSUED DURING CONSTRUCTION
GENERAL					
G-000	COVER SHEET				
ARCHITEC	TURAL				
A-101	ROOF PLAN				
A-102	ROOF PHOTOGRAPHS	•			
A-201	WEST ELEVATIONS				
A-202	NORTH ELEVATIONS				
A-202 A-203	NORTH ELEVATIONS EAST ELEVATIONS	•			
A-203	EAST ELEVATIONS				

ISSUED FOR BOSTON LANDMARKS COMMISSION 02/01/21 CONSTRUCTION LANDMARKS COMMISSION 02/01/21 CONSTRUCTION LANDMARKS COMMISSION 02/01/21



EXISTING ROOF PLAN

GENERAL RESTORATION NOTES

- INSTALL NEW SLATE SHINGLES TO MATCH EXISTING SIZE, COLOR, AND HEAD LAP.
- 2. REPAIR DAMAGED ROOF FLASHINGS.

KEY NOTES

- REPAIR/ REPLACE MOVING, DAMAGED, OR MISSING SLATE SHINGLES. REFER TO KEY TAG FOR LOCATIONS.
- REPLACE EXISTING ROOF MEMBRANE WITH NEW FLAT SEAM COPPER ROOF WITH RUBBER ROOF PAVERS AT THIRD FLOOR FIRE ESCAPE DOOR.
- ROUTE AND SEAL CRACKS IN CONCRETE CHIMNEY CAPS. NEW SEALANT TO HAVE SANDED FACE TO MATCH EXISTING CONCRETE.
- $\langle 4 \rangle$ NEW FLAT SEAM COPPER ROOF OVER NEW CONSTRUCTION AT MUDROOM.
- 5 REMOVE EXISTING METAL ROOFS.
- $\langle 6 \rangle$ INSTALL NEW ENGINEERED SNOW GUARD SYSTEM.
- 7 EXISTING ROOF VENT TO REMAIN.
- 8 EXISTING FIRE ESCAPE NOT SHOWN FOR CLARITY.
- $|9\rangle$ NEW FLAT SEAM COPPER ROOFS TO MATCH EXISTING.

KEY

MISSING / DAMAGED SLATE

WESSLING ARCHITECTS AIA-CSI-BOCA

PRESIDENTS PLACE, 1250 HANCOCK STREET, SUITE 815N QUINCY, MA 02169 TEL. 617-773-8150 FAX 617-773-4902 www.wesslingarchitects.com

CONSULTANTS:

CURLEY HOUSE EXTERIOR RESTORATION

350 JAMAICAWAY JAMAICA PLAIN, MA

CITY OF BOSTON

1 CITY HALL SQUARE BOSTON, MA

PROFESSIONAL

PREPARED BY A LICENSED ARCHITECT
Any changes to this item can be a violation of the law unless altered by a licensed architect. Any alteration made to this item must be accompanied by a specific description of change or changes made; date change was made, as well as the seal of the licensed architect who made or oversaw the


MARK DATE DESCRIPTION

PROJECT NO.:	20130	8
DRAWN BY:	LAW	
CHECKED BY:	SAW	Ç
DRAWING SCALE:	AS NOTED	


SHEET TITLE:

ROOF PLAN

TYPICAL SLATE ROOF



TYPICAL DORMER AND VENT PIPE



TYPICAL GUTTER CONDITION



FAILED SEALANT AT FLASHING








STEEP SLOPE SLATE ROOF









DAMAGE AT ROOF DORMER - WEST




ROOF DORMERS - WEST








(10) FIRE ESCAPE AND TYPICAL ROOF








SUNROOM ROOF



MUDROOM ROOF

14 MUDROOM ROOF



FIRE ESCAPE AND TYPICAL ROOF



ROOF DORMERS - EAST

CONSULTANTS:

CURLEY HOUSE EXTERIOR RESTORATION

WESSLING

QUINCY, MA 02169 TEL. 617-773-8150 FAX 617-773-4902 www.wesslingarchitects.com

ARCHITECTS

AIA-CSI-BOCA

350 JAMAICAWAY JAMAICA PLAIN, MA

CITY OF BOSTON

1 CITY HALL SQUARE BOSTON, MA

PROFESSIONAL

PREPARED BY A LICENSED ARCHITECT
Any changes to this item can be a violation of the law unless altered by a licensed architect. Any alteration made to this item must be accompanied by a specific description of change or changes made; date change was made, as well as the seal of the licensed architect who made or oversaw the

	02-01-21	BLC SUBMISSION	
MARK	DATE	DESCRIPTION	
ISSUE:			
PROJECT NO.:		20130	
DRAWN BY:		LAW	
CHECKED BY:		SVW	

AS NOTED DRAWING SCALE: SHEET TITLE:

ROOF **PHOTOGRAPHS**

A-102



WEST ELEVATION (JAMAICAWAY) - PROPOSED



WEST ELEVATION (JAMAICAWAY) - EXISTING

1/4"=1'-0"

GENERAL RESTORATION NOTES

- NEW MORTAR TO MATCH EXISTING ORIGINAL MORTAR IN COLOR, TEXTURE, STRENGTH, AND TOOLING. PROVIDE MOCK-UP FOR ARCHITECT AND BOSTON LANDMARKS COMMISSION REVIEW AND APPROVAL.
- WOOD REPAIRS TO BE PERFORMED WITH WOOD DUTCHMAN OR WOOD COMPONENT
 2. REPLACEMENT WITH THE SAME WOOD SPECIES WHEN POSSIBLE. REPAIRS TO BE PERFORMED
- TO MINIMIZE THE AMOUNT OF ORIGINAL MATERIAL BEING REMOVED.

 PREPARE AND REPAINT ALL WOOD WALLS, TRIM, FASCIA, SOFFITS ETC.


NEW PAINT TO MATCH EXISTING PAINT COLOR AND SHEEN.

- TYPICAL WINDOW SCOPE: SELECTIVELY REPAIR DAMAGED WOOD WINDOW FRAME, SILL, AND SASH ELEMENTS WITH NEW WOOD. REMOVE EXISTING PAINT AND REPAINT ALL WOOD ELEMENTS. INSTALL NEW WEATHERSTRIPPING.
- 5. ALL EXTERIOR DOORS TO BE PREPARED AND PAINTED.
- INSTALL HISTORICALLY APPROPRIATE REMOVABLE STORM WINDOWS (MARVIN STORM SCREENS)
 TO IMPROVE THERMAL PERFORMANCE OF WINDOWS AND EXTEND THE SERVICE LIFE OF WINDOW GLAZING AND PAINT.


KEY NOTES

- OPEN MORTAR JOINTS. REPOINT OPEN DETERIORATING JOINTS DEEPER THAN ¼" AT APPROXIMATELY 5% OF THE MASONRY WALLS.
- REPOINTED JOINTS WITH NEWER MISMATCHED MORTAR. APPLY A STAIN TO THE NEW MORTAR TO HELP BLEND IT IN WITH THE OLDER MORTAR.
- REPLACE EXISTING ALUMINUM WINDOWS AT EAST ELEVATION WITH NEW WOOD REPLICA SASH IN THE EXISTING WOOD FRAME.
- REPAIR DAMAGED DECORATIVE COPPER AT THE WEST FACING DORMERS.
- $\langle 5 \rangle$ REPAINT IRON BALCONIES ON THE WEST ELEVATION.
- REMOVE PLYWOOD PANELS TO EXPOSE ORIGINAL WOOD PILASTERS AND WALL PANELING BEHIND. REPAIR DAMAGED WOOD AND REPAINT.
- ROTTED WOOD CLADDING, TRIM, AND SILLS AT ENCLOSED PORCH ON EAST ELEVATION. REMOVE AND CONSTRUCT NEW MUDROOM/ ACCESSIBLE ENTRANCE WITH MORE HISTORICALLY
- APPROPRIATE DESIGN. REFER TO THE PROPOSED ELEVATIONS FOR MORE INFORMATION.

 REMOVE EXISTING METAL FRAMED CANOPY ROOFS AND REPLACE WITH WOOD FRAMED ROOFS WITH WOOD TRIM AND COPPER ROOFS SIMILAR TO EXISTING.
- 9 REPAIR ROTTED WOOD TRIM AND SILL, TYPICAL.
- $\langle 10 \rangle$ REBUILD DISPLACED MASONRY WITH EXISTING BRICK OR NEW TO MATCH EXISTING.
- 11 REPAIR HOLES IN MASONRY WITH NEW COLOR MATCHED MORTAR.
- $\langle 12 \rangle$ EXISTING FIRE ESCAPE NOT SHOWN FOR CLARITY.
- (13) REPAIR CONCRETE AND APPLY TRAFFIC WATERPROOFING SYSTEM TO TOP SURFACE.
- INSTALL NEW ENGINEERED SNOW GUARD SYSTEM TO PREVENT FUTURE SLIDING ICE AND SNOW DAMAGE.
- (15) REPAIR, REPAINT, AND REINSTALL MISSING SHUTTER FOUND ON SITE.
- $\langle 16 \rangle$ NEW FOUR PANEL WOOD DOOR IN EXISTING WOOD FRAME.
- (17) REPAIR DAMAGED COLUMN BASES.
- (18) REBUILD BALUSTRADE WITH BRICK COLUMNS AND PRECAST CONCRETE CAPS.
- 19 NEW SQUARE WOOD COLUMNS.
- (20) REPLACE MISSING MUNTINS IN WINDOW SASH.
- 21 RELOCATE EXISTING FENCE POST TO OPPOSITE CORNER.
- REPAIR BROKEN STAINED GLASS PIECES AND INSTALL NEW VENTED EXTERIOR STORM WINDOW.



WINDOW JAMB DETAIL - HEAD SIMILAR



WINDOW SILL AND MUNTIN DETAIL

3"=1'-0"

WESSLING
ARCHITECTS
AIA-CSI-BOCA

PRESIDENTS PLACE, 1250 HANCOCK STREET, SUITE 815N QUINCY, MA 02169 TEL. 617-773-8150 FAX 617-773-4902 www.wesslingarchitects.com

CONSULTANTS:

PO IECT:

CURLEY HOUSE EXTERIOR RESTORATION

350 JAMAICAWAY JAMAICA PLAIN, MA

LIENT:

CITY OF BOSTON

1 CITY HALL SQUARE BOSTON, MA

NOTFORTION

PREPARED BY A LICENSED ARCHITECT

Any changes to this item can be a violation of the law unless altered by a licensed architect. Any alteration made to this item must be accompanied by a specific description of change or changes made; date change was made, as well as the seal of the

licensed architect who made or oversaw the

	02-01-21	BLC SUBMISSION
IARK	DATE	DESCRIPTION
SSUE:		

PROJECT NO.: 20130

DRAWN BY: LAW

CHECKED BY: SAW

DRAWING SCALE: AS NOTED


SHEET TITLE: WEST

NEW WOOD STORM

WINDOW SET INTO EXISTING FRAME

WEST ELEVATIONS

A-201



GENERAL RESTORATION NOTES

- NEW MORTAR TO MATCH EXISTING ORIGINAL MORTAR IN COLOR, TEXTURE, STRENGTH, AND TOOLING. PROVIDE MOCK-UP FOR ARCHITECT AND BOSTON LANDMARKS COMMISSION REVIEW AND APPROVAL.
- WOOD REPAIRS TO BE PERFORMED WITH WOOD DUTCHMAN OR WOOD COMPONENT
 2. REPLACEMENT WITH THE SAME WOOD SPECIES WHEN POSSIBLE. REPAIRS TO BE PERFORMED
- 3. PREPARE AND REPAINT ALL WOOD WALLS, TRIM, FASCIA, SOFFITS ETC NEW PAINT TO MATCH EXISTING PAINT COLOR AND SHEEN.

TO MINIMIZE THE AMOUNT OF ORIGINAL MATERIAL BEING REMOVED.

- TYPICAL WINDOW SCOPE: SELECTIVELY REPAIR DAMAGED WOOD WINDOW FRAME, SILL, AND SASH ELEMENTS WITH NEW WOOD. REMOVE EXISTING PAINT AND REPAINT ALL WOOD ELEMENTS. INSTALL NEW WEATHERSTRIPPING.
- 5. ALL EXTERIOR DOORS TO BE PREPARED AND PAINTED.
- INSTALL HISTORICALLY APPROPRIATE REMOVABLE STORM WINDOWS (MARVIN STORM SCREENS)
 TO IMPROVE THERMAL PERFORMANCE OF WINDOWS AND EXTEND THE SERVICE LIFE OF WINDOW GLAZING AND PAINT.

KEY NOTES

- OPEN MORTAR JOINTS. REPOINT OPEN DETERIORATING JOINTS DEEPER THAN ¼" AT APPROXIMATELY 5% OF THE MASONRY WALLS.
- 2 REPOINTED JOINTS WITH NEWER MISMATCHED MORTAR. APPLY A STAIN TO THE NEW MORTAR TO HELP BLEND IT IN WITH THE OLDER MORTAR.
- REPLACE EXISTING ALUMINUM WINDOWS AT EAST ELEVATION WITH NEW WOOD REPLICA SASH IN THE EXISTING WOOD FRAME.
- $\left\langle 4 \right\rangle$ REPAIR DAMAGED DECORATIVE COPPER AT THE WEST FACING DORMERS.
- 5 REPAINT IRON BALCONIES ON THE WEST ELEVATION.
- REMOVE PLYWOOD PANELS TO EXPOSE ORIGINAL WOOD PILASTERS AND WALL PANELING BEHIND. REPAIR DAMAGED WOOD AND REPAINT.
- ROTTED WOOD CLADDING, TRIM, AND SILLS AT ENCLOSED PORCH ON EAST ELEVATION. REMOVE
- AND CONSTRUCT NEW MUDROOM/ ACCESSIBLE ENTRANCE WITH MORE HISTORICALLY APPROPRIATE DESIGN. REFER TO THE PROPOSED ELEVATIONS FOR MORE INFORMATION.
- REMOVE EXISTING METAL FRAMED CANOPY ROOFS AND REPLACE WITH WOOD FRAMED ROOFS WITH WOOD TRIM AND COPPER ROOFS SIMILAR TO EXISTING.
- $\langle 9 \rangle$ REPAIR ROTTED WOOD TRIM AND SILL, TYPICAL.
- $\langle 10 \rangle$ REBUILD DISPLACED MASONRY WITH EXISTING BRICK OR NEW TO MATCH EXISTING.
- $\langle 11 \rangle$ REPAIR HOLES IN MASONRY WITH NEW COLOR MATCHED MORTAR.
- $|\langle 12 \rangle|$ EXISTING FIRE ESCAPE NOT SHOWN FOR CLARITY.
- REPAIR CONCRETE AND APPLY TRAFFIC WATERPROOFING SYSTEM TO TOP SURFACE.
- INSTALL NEW ENGINEERED SNOW GUARD SYSTEM TO PREVENT FUTURE SLIDING ICE AND SNOW DAMAGE.
- (15) REPAIR, REPAINT, AND REINSTALL MISSING SHUTTER FOUND ON SITE.
- $\langle 16 \rangle$ NEW FOUR PANEL WOOD DOOR IN EXISTING WOOD FRAME.
- 17 REPAIR DAMAGED COLUMN BASES.
- $|\langle 18 \rangle|$ REBUILD BALUSTRADE WITH BRICK COLUMNS AND PRECAST CONCRETE CAPS.
- 19 NEW SQUARE WOOD COLUMNS.
- REPLACE MISSING MUNTINS IN WINDOW SASH.
- 21 RELOCATE EXISTING FENCE POST TO OPPOSITE CORNER.
- REPAIR BROKEN STAINED GLASS PIECES AND INSTALL NEW VENTED EXTERIOR STORM WINDOW.



PRESIDENTS PLACE, 1250 HANCOCK STREET, SUITE 815N QUINCY, MA 02169 TEL. 617-773-8150 FAX 617-773-4902 www.wesslingarchitects.com

CONSULTANTS:

ROJECT:

CURLEY HOUSE EXTERIOR RESTORATION

350 JAMAICAWAY JAMAICA PLAIN, MA

CLIENT:

CITY OF BOSTON

1 CITY HALL SQUARE BOSTON, MA

> NOT FOR TON NOT RUCTION PROFESSIONAL

PREPARED BY A LICENSED ARCHITECT
Any changes to this item can be a violation of the law unless altered by a licensed architect. Any alteration made to this item must be accompanied by a specific description of change or changes made; date change was made, as well as the seal of the licensed architect who made or oversaw the

02-01-21 BLC SUBMISSION

MARK DATE DESCRIPTION

PROJECT NO.: 20130

DRAWN BY: LAW

CHECKED BY: SAW

DRAWING SCALE: AS NOTED

SHEET TITLE:

NORTH ELEVATIONS

A-202



GENERAL RESTORATION NOTES

- NEW MORTAR TO MATCH EXISTING ORIGINAL MORTAR IN COLOR, TEXTURE, STRENGTH, AND TOOLING. PROVIDE MOCK-UP FOR ARCHITECT AND BOSTON LANDMARKS COMMISSION REVIEW
- WOOD REPAIRS TO BE PERFORMED WITH WOOD DUTCHMAN OR WOOD COMPONENT REPLACEMENT WITH THE SAME WOOD SPECIES WHEN POSSIBLE. REPAIRS TO BE PERFORMED
- TO MINIMIZE THE AMOUNT OF ORIGINAL MATERIAL BEING REMOVED. PREPARE AND REPAINT ALL WOOD WALLS, TRIM, FASCIA, SOFFITS ETC
- NEW PAINT TO MATCH EXISTING PAINT COLOR AND SHEEN.
- TYPICAL WINDOW SCOPE: SELECTIVELY REPAIR DAMAGED WOOD WINDOW FRAME, SILL, AND SASH ELEMENTS WITH NEW WOOD. REMOVE EXISTING PAINT AND REPAINT ALL WOOD ELEMENTS. INSTALL NEW WEATHERSTRIPPING.
- ALL EXTERIOR DOORS TO BE PREPARED AND PAINTED.
- NSTALL HISTORICALLY APPROPRIATE REMOVABLE STORM WINDOWS (MARVIN STORM SCREENS) TO IMPROVE THERMAL PERFORMANCE OF WINDOWS AND EXTEND THE SERVICE LIFE OF WINDOW GLAZING AND PAINT.

KEY NOTES

- OPEN MORTAR JOINTS. REPOINT OPEN DETERIORATING JOINTS DEEPER THAN ¼" AT APPROXIMATELY 5% OF THE MASONRY WALLS.
- REPOINTED JOINTS WITH NEWER MISMATCHED MORTAR. APPLY A STAIN TO THE NEW MORTAR TO
- \angle HELP BLEND IT IN WITH THE OLDER MORTAR. REPLACE EXISTING ALUMINUM WINDOWS AT EAST ELEVATION WITH NEW WOOD REPLICA SASH IN THE EXISTING WOOD FRAME.
- $\left\langle 4 \right\rangle$ REPAIR DAMAGED DECORATIVE COPPER AT THE WEST FACING DORMERS.
- \langle 5 \rangle REPAINT IRON BALCONIES ON THE WEST ELEVATION.
- REMOVE PLYWOOD PANELS TO EXPOSE ORIGINAL WOOD PILASTERS AND WALL PANELING
- BEHIND. REPAIR DAMAGED WOOD AND REPAINT. ROTTED WOOD CLADDING, TRIM, AND SILLS AT ENCLOSED PORCH ON EAST ELEVATION. REMOVE
- AND CONSTRUCT NEW MUDROOM/ ACCESSIBLE ENTRANCE WITH MORE HISTORICALLY APPROPRIATE DESIGN. REFER TO THE PROPOSED ELEVATIONS FOR MORE INFORMATION.
- REMOVE EXISTING METAL FRAMED CANOPY ROOFS AND REPLACE WITH WOOD FRAMED ROOFS WITH WOOD TRIM AND COPPER ROOFS SIMILAR TO EXISTING.
- $\langle \,\,\,
 angle \,\,
 angle$ REPAIR ROTTED WOOD TRIM AND SILL, TYPICAL.
- $\langle 10 \rangle$ REBUILD DISPLACED MASONRY WITH EXISTING BRICK OR NEW TO MATCH EXISTING.
- \langle 11 \rangle REPAIR HOLES IN MASONRY WITH NEW COLOR MATCHED MORTAR.
- \langle 12 angle EXISTING FIRE ESCAPE NOT SHOWN FOR CLARITY
- (13) REPAIR CONCRETE AND APPLY TRAFFIC WATERPROOFING SYSTEM TO TOP SURFACE.
- INSTALL NEW ENGINEERED SNOW GUARD SYSTEM TO PREVENT FUTURE SLIDING ICE AND SNOW DAMAGE.
- 15 REPAIR, REPAINT, AND REINSTALL MISSING SHUTTER FOUND ON SITE.

- \langle 17 \rangle REPAIR DAMAGED COLUMN BASES.
- \langle 18 angle REBUILD BALUSTRADE WITH BRICK COLUMNS AND PRECAST CONCRETE CAPS.
- 19 NEW SQUARE WOOD COLUMNS.
- $\left| \left\langle 20 \right\rangle \right|$ REPLACE MISSING MUNTINS IN WINDOW SASH.
- 21 RELOCATE EXISTING FENCE POST TO OPPOSITE CORNER.
- $\langle 22 \rangle$ REPAIR BROKEN STAINED GLASS PIECES AND INSTALL NEW VENTED EXTERIOR STORM WINDOW.
- 23 LOWER EXISTING LANDING AND CREATE NEW STEPS TO GRADE.



PRESIDENTS PLACE, 1250 HANCOCK STREET, SUITE 815N QUINCY, MA 02169 TEL. 617-773-8150 FAX 617-773-4902 www.wesslingarchitects.com

CONSULTANTS:

CURLEY HOUSE EXTERIOR RESTORATION

350 JAMAICAWAY JAMAICA PLAIN, MA

CITY OF **BOSTON**

1 CITY HALL SQUARE BOSTON, MA

PROFESSIONAL

PREPARED BY A LICENSED ARCHITECT Any changes to this item can be a violation of the law unless altered by a licensed architect. Any alteration made to this item must be accompanied by a specific description of change or changes made; date change was made, as well as the seal of the licensed architect who made or oversaw the

MARK DATE DESCRIPTION


20130 PROJECT NO.: DRAWN BY: LAW

SAW CHECKED BY: AS NOTED DRAWING SCALE: SHEET TITLE:

EAST **ELEVATIONS**



SOUTH ELEVATION - PROPOSED



GENERAL RESTORATION NOTES

- NEW MORTAR TO MATCH EXISTING ORIGINAL MORTAR IN COLOR, TEXTURE, STRENGTH, AND TOOLING. PROVIDE MOCK-UP FOR ARCHITECT AND BOSTON LANDMARKS COMMISSION REVIEW AND APPROVAL.
- WOOD REPAIRS TO BE PERFORMED WITH WOOD DUTCHMAN OR WOOD COMPONENT
 2. REPLACEMENT WITH THE SAME WOOD SPECIES WHEN POSSIBLE. REPAIRS TO BE PERFORMED
- TO MINIMIZE THE AMOUNT OF ORIGINAL MATERIAL BEING REMOVED.

 PREPARE AND REPAINT ALL WOOD WALLS, TRIM, FASCIA, SOFFITS ETC.

NEW PAINT TO MATCH EXISTING PAINT COLOR AND SHEEN.

- TYPICAL WINDOW SCOPE: SELECTIVELY REPAIR DAMAGED WOOD WINDOW FRAME, SILL, AND SASH ELEMENTS WITH NEW WOOD. REMOVE EXISTING PAINT AND REPAINT ALL WOOD ELEMENTS. INSTALL NEW WEATHERSTRIPPING.
- 5. ALL EXTERIOR DOORS TO BE PREPARED AND PAINTED.
- INSTALL HISTORICALLY APPROPRIATE REMOVABLE STORM WINDOWS (MARVIN STORM SCREENS)

 TO IMPROVE THERMAL PERFORMANCE OF WINDOWS AND EXTEND THE SERVICE LIFE OF WINDOW GLAZING AND PAINT.

KEY NOTES

- OPEN MORTAR JOINTS. REPOINT OPEN DETERIORATING JOINTS DEEPER THAN ¼" AT APPROXIMATELY 5% OF THE MASONRY WALLS.
- REPOINTED JOINTS WITH NEWER MISMATCHED MORTAR. APPLY A STAIN TO THE NEW MORTAR TO HELP BLEND IT IN WITH THE OLDER MORTAR.
- REPLACE EXISTING ALUMINUM WINDOWS AT EAST ELEVATION WITH NEW WOOD REPLICA SASH IN THE EXISTING WOOD FRAME.
- $\left\langle 4 \right\rangle$ REPAIR DAMAGED DECORATIVE COPPER AT THE WEST FACING DORMERS.
- 5 REPAINT IRON BALCONIES ON THE WEST ELEVATION.
- REMOVE PLYWOOD PANELS TO EXPOSE ORIGINAL WOOD PILASTERS AND WALL PANELING BEHIND. REPAIR DAMAGED WOOD AND REPAINT.
- ROTTED WOOD CLADDING, TRIM, AND SILLS AT ENCLOSED PORCH ON EAST ELEVATION. REMOVE
- AND CONSTRUCT NEW MUDROOM/ ACCESSIBLE ENTRANCE WITH MORE HISTORICALLY APPROPRIATE DESIGN. REFER TO THE PROPOSED ELEVATIONS FOR MORE INFORMATION.

 REMOVE EXISTING METAL FRAMED CANOPY ROOFS AND REPLACE WITH WOOD FRAMED ROOFS WITH WOOD TRIM AND COPPER ROOFS SIMILAR TO EXISTING.
- 9 REPAIR ROTTED WOOD TRIM AND SILL, TYPICAL.
- 10 REBUILD DISPLACED MASONRY WITH EXISTING BRICK OR NEW TO MATCH EXISTING.
- 11 REPAIR HOLES IN MASONRY WITH NEW COLOR MATCHED MORTAR.
- (12) EXISTING FIRE ESCAPE NOT SHOWN FOR CLARITY.
- 13 REPAIR CONCRETE AND APPLY TRAFFIC WATERPROOFING SYSTEM TO TOP SURFACE.
- 14 INSTALL NEW ENGINEERED SNOW GUARD SYSTEM TO PREVENT FUTURE SLIDING ICE AND SNOW DAMAGE.
- 15 REPAIR, REPAINT, AND REINSTALL MISSING SHUTTER FOUND ON SITE.
- 16 NEW FOUR PANEL WOOD DOOR IN EXISTING WOOD FRAME.
- 17 REPAIR DAMAGED COLUMN BASES.
- $|\langle 18 \rangle|$ REBUILD BALUSTRADE WITH BRICK COLUMNS AND PRECAST CONCRETE CAPS.
- 19 NEW SQUARE WOOD COLUMNS.
- $|\langle 20 \rangle|$ REPLACE MISSING MUNTINS IN WINDOW SASH.
- 21 RELOCATE EXISTING FENCE POST TO OPPOSITE CORNER.
- REPAIR BROKEN STAINED GLASS PIECES AND INSTALL NEW VENTED EXTERIOR STORM WINDOW.



PRESIDENTS PLACE, 1250 HANCOCK STREET, SUITE 815N QUINCY, MA 02169 TEL. 617-773-8150 FAX 617-773-4902 www.wesslingarchitects.com

CONSULTANTS:

O IECT:

CURLEY HOUSE EXTERIOR RESTORATION

350 JAMAICAWAY JAMAICA PLAIN, MA

LIENT:

CITY OF BOSTON

1 CITY HALL SQUARE BOSTON, MA

NOT FOR TO TO THE PROFESSIONAL

PREPARED BY A LICENSED ARCHITECT
Any changes to this item can be a violation of the law unless altered by a licensed architect. Any alteration made to this item must be accompanied by a specific description of change or changes made; date change was made, as well as the seal of the licensed architect who made or oversaw the

02-01-21 BLC SUBMISSION

MARK DATE DESCRIPTION

PROJECT NO.: 20130

DRAWN BY: LAW

CHECKED BY: SAW

DRAWING SCALE: AS NOTED


SOUTH ELEVATIONS

A-204


DO NOT SCALE DRAWING

1 SOUTH ELEVATION - EXISTING
1/4"=1'-0"

(20) REMAINS OF EXISTING BALUSTRADE



DAMAGE AT DOOR




MASONRY JOINTS TO BE REPOINTED



8 DAMAGED CAPITAL AT DORMER



EAST AND SOUTH ELEVATIONS









NORTH ELEVATION





WEST ELEVATION



MUDROOM - EAST ELEVATION

MUDROOM - NORTH ELEVATION



DETERIORATING COLUMN BASES

SUNROOM_




MASONRY JOINTS TO BE STAINED






9 WINDOWS TO BE REPLACED



SOUTH ELEVATION



PROFESSIONAL

WESSLING

QUINCY, MA 02169 TEL. 617-773-8150 FAX 617-773-4902 www.wesslingarchitects.com

CURLEY HOUSE

EXTERIOR

RESTORATION

350 JAMAICAWAY JAMAICA PLAIN, MA

CITY OF

BOSTON

1 CITY HALL SQUARE BOSTON, MA

ARCHITECTS

AIA-CSI-BOCA

PREPARED BY A LICENSED ARCHITECT
Any changes to this item can be a violation of the law unless altered by a licensed architect. Any alteration made to this item must be accompanied by a specific description of change or changes made; date change was made, as well as the seal of the licensed architect who made or oversaw the

	02-01-21	BLC SUBMISSION
ARK	DATE	DESCRIPTION
SSUE:		

		2
PROJECT NO.:	20130	. 20
DRAWN BY:	LAW	NC
CHECKED BY:	SAW	TS
DRAWING SCALE:	AS NOTED	TEC

SHEET TITLE: **ELEVATION PHOTOGRAPHS**

A-205

REMOVE EXISTING SIDEWALK

REMOVE EXISTING DAMAGED FENCE AND CONSTRUCT NEW

\ REFERENCE DRAWING - TOPOGRAPHICAL MAP 1915

EXISTING SITE PLAN








GARAGE - WEST ELEVATION





GARAGE - EXISTING NORTH ELEVATION






GARAGE - NORTH ELEVATION

KEY NOTES

- 1 INSTALL NEW ROLL-UP CARRIAGE HOUSE DOOR.
- RESTORE EXISTING DECORATIVE WOOD FENCE POSTS. INSTALL NEW SQUARE LATTICE FENCE.
- 3 INSTALL NEW WOOD BASES AT PILASTERS.
- 4 BUILD NEW PILASTER AT CENTER POST.
- 5 NEW SIX PANEL WOOD DOOR IN EXISTING WOOD FRAME.
- 6 REPAIR DAMAGED MASONRY AROUND RUSTED LINTELS.



PROPOSED SITE PLAN

REFERENCE DRAWING - PLANTING PLAN 1916

-INSTALL NEW SIDEWALK CENTERED
ON PROPOSED ENTRANCE

—INSTALL NEW FENCE WITH RESTORED DECORATIVE FENCE POSTS

GARAGE - EXISTING WEST ELEVATION

GARAGE - PROPOSED NORTH ELEVATION

GARAGE - PROPOSED WEST ELEVATION

DO NOT SCALE DRAWING

WESSLING

PRESIDENTS PLACE, 1250 HANCOCK STREET, SUITE 815N QUINCY, MA 02169 TEL. 617-773-8150 FAX 617-773-4902 www.wesslingarchitects.com

CURLEY HOUSE

EXTERIOR

RESTORATION

350 JAMAICAWAY JAMAICA PLAIN, MA

CITY OF

BOSTON

1 CITY HALL SQUARE BOSTON, MA

PREPARED BY A LICENSED ARCHITECT
Any changes to this item can be a violation of the law unless altered by a licensed architect. Any

alteration made to this item must be accompanied by

a specific description of change or changes made; date change was made, as well as the seal of the licensed architect who made or oversaw the

02-01-21 BLC SUBMISSION

20130

LAW

SAW

AS NOTED

SITE PLANS AND GARAGE

ELEVATIONS

MARK DATE DESCRIPTION

PROJECT NO.:

DRAWN BY:

CHECKED BY:

SHEET TITLE:

DRAWING SCALE:

PROFESSIONAL

CONSULTANTS:

ARCHITECTS

AIA-CSI-BOCA