## RYDER/JONES RESIDENCE

45 Mount Vernon Street

Boston, MA


FOR BHAC REVIEW

05.26.21

## **CONTENTS:**

PAGE 1	COVER
PAGE 2	LOCUS PLAN
PAGE 3	PHOTOS FROM A PUBLIC WAY OF SIGHT LINES
PAGE 4	PHOTOS FROM A PUBLIC WAY OF SIGHT LINES (WITH RAILING MOCK UP AT DECK AND RENDERED PHOTO OF FRONT GLAZED HEAD HOUSE/SKYLIGHT)
PAGE 5	PHOTOS OF EXISTING CONDITIONS
PAGE 6	PHOTOS OF PREVIOUSLY APPROVED DECK PRIOR TO DEMO
PAGE 7	PHOTOS OF DECK WITH MOCK UP
PAGE 8	EXISTING CONDITIONS FLOOR PLANS
PAGE 9	PROPOSED PLANS
PAGE 10	PROPOSED ELEVATIONS
PAGE 11	PROPOSED REPLACEMENT DRAWINGS AND SPECIFICATIONS FOR GLAZED HEAD HOUSE/SKYLIGHT






LOCUS VIEW



Ryder/Jones Residence 45 Mount Vernon Street Boston, MA 05.26.21



Close-up of glazed head house with skylight to be replaced due to failing seals. It will have with the same footprint and height as previously approved.





A View from joy street looking up at the solarium.



Close-up of view of where the proposed reinstated deck with

a wrought iron railing painted matte black would be visible,



View from Pinckney Street looking up at proposed reinstated deck and railing.



Close up view from Pinckney Street looking up at proposed reinstated deck and railing. Human for scale, is leaning on the 2 x 4 mock up railing.

Close up from Pinckney Street looking up at former deck railing (prior to demo) seen through the downstairs neighbor's railing.

Close up of rendered image illustrating new glazed head house skylight to mimic existing with bronze exterior frame. The replacement frame and glass will be squared off rather than have the rounded design. The new glass has a higher R-value and as such, will be slightly darker in hue.

Ryder/Jones Residence 45 Mount Vernon Street Boston, MA 05.26.21












View from Pinckney Street looking up at proposed reinstated deck and railing.



View from Pinckney Street looking up at former deck railing behind downstairs neighbor's railing.




View from Pinckney Street looking up at an altered photo showing the new bronze square frame of the glazed head house skylight.






Existing conditions of deteriorated glazed head house and skylight with failing seals and worn cedar cladding.

Α



В



C




D



E

Original certificate of appropriateness for the glazed head house and skylight that is marginally visible from Joy Street.



Ryder/Jones Residence 45 Mount Vernon Street Boston, MA 05.26.21



Broken seals with condensation in panes. Photo taken from inside, looking up.





PHOTO KEY









PHOTO KEY





Original approved deck that was torn down for a roof replacement. We are seeking permission to replace in the same footprint as previously approved, with an architecturally appropriate railing. See drawings.










PHOTO KEY

Α



Mock up shows deck at 3 feet from leading edge of roof and a code compliant railing of 42" above the decking.









SCALE: 1/4"= 12" ROOF DECK - EXISTING CONDITIONS









New glazed head house and skylight to have the same footprint and divided frame configuration. Proposed change is to eliminate the quarter round arch in favor of a squared off frame that marries with the architecture of the neighborhood. Frame to have a dark bronze powder coating at the exterior frame and due to the higher R-rating, teh glass will we a few shades darker than what is currently in place.

