D.Ma							Woburn, MA (Change)	Sup	port Career	s Pella Luxu	ury Division	n Get a Quote	
Felin	Windows 🗸	Doors 🗸	Performance 🗸	How to Buy	For Pros 🖌						Q Search	8 Sign In	, j
		Pella® Reserve™ - Traditional Double-Hung Window - Wood											
		+ Expand All											
		+ Design,	Performance & Size	e Tables	+ 2D Cro	oss Section			+ Product Li	terature			
		+ Specifica	ations		+ 2D Ele	vation							
		View Product	Details >										
	_	Pella® Architect Series - Traditional Double-Hung Window - Wood											
		+ Expand All											
		+ Design,	Performance & Size	e Tables	+ 2D Cro	oss Section			+ Product Li	terature			
		+ Specifica	ations		+ 2D Ele	vation							
		View Product	Details >										

Boston Landmark Commission (BLC) – Application #22.0631 SE: 89 WALTHAM STREET #5 South End Landmark District Commission (SELDC) - Public Hearing, 01/04/2022: PRESENTATION INFORMATION

Two (2) Viable Options for Acceptance and Approval of One (1) New Replacement Wood Window:

- 1) Pella Reserve Traditional Double-Hung Window Wood
- 2) Pella Architect Series Traditional Double-Hung Window Wood

Note:

- a) Applicant has met with a Pella representative for an introduction at the company's showroom; a field measurement has been scheduled.
- b) Per meeting with the Pella representative, it is the Applicant's understanding that the 2 viable options (the brand's wood window series) listed above contain detail options to conform with historical district guidelines, such as the grilles.
- c) Applicant has been informed by the Pella representative that supply chain and lead time issue of pending orders are eminent no timeframe provided by the representative at this time.
- d) If both viable options are acceptable for approval, Applicant wish to seek advisory from BLC/SELDC for final selection. This wish is due primarily in part by the cost and first availability due to Applicant's projected supply chain concern.

Thanks.



Existing window to be replaced—at the right facing street; 1 level below top floor (Photo Reference - View 1 of 2)



Existing window to be replaced—at the right facing street; 1 level below top floor (Photo Reference - View 2 of 2)