


Portions of existing PIP rubber surfacing to remain.



Existing fence to remain and be touched-up.



Existing bench to be relocated on-site.



Damaged existing fence on concrete wall to be repaired/replaced to match existing.



Existing light poles to remain.





Existing 2 - 5 climber to be removed.

ELLIS EARLY LEARNING CHILDREN'S PARK



Existing Site Elements





ELLIS EARLY LEARNING CHILDREN'S PARK Existing Conditions - Views From Outside of Playground

5






2. View of playground from Chandler St.






3. View of walkway from Chandler St.



5. View of playground and trees from Tremont Plaza

ELLIS EARLY LEARNING CHILDREN'S PARK Existing Conditions - Views From Outside of Playground









2. View of climber, benches and tree grates from Chandler St.

ELLIS EARLY LEARNING CHILDREN'S PARK Existing Conditions - Views From Inside of Playground



5' 10' 20'










5. View of gate and light pole looking towards Tremont Plaza



and the Mass Pike

studio MLA ARCHITECTS

ELLIS EARLY LEARNING CHILDREN'S PARK Existing Conditions - Views From Inside of Playground



SIDEWALK

studio MLA ARCHITECTS

ELLIS EARLY LEARNING CHILDREN'S PARK

Proposed Site Plan

Playshaper Treehouse Climber

EQUIPMENT COLORS

Liriope Muscari

studio

ARCHITECTS

Brown STEEL DECKS Stairs and decks













ELLIS EARLY LEARNING CHILDREN'S PARK

Proposed Site Elements



Horizontal Log & Hill Slide





IPE Wood Stage















