

238 Marlborough Street


Façade Restoration

Landmarks Hearing June 14th, 2023

Springer Architects

Project Description:

- Restoration of the North and South Facades in kind.
- Repoint brickwork on North and South facades as well as 5th floor East and West facades.
- Remove brick staining and efflorescence.
- Repair all damaged brownstone and paint with Tammscoat waterproof paint, HC69.
- Restore metal mansard window surrounds in kind and paint with Tammscoat color HC69.
- Restore and make weather tight front door in kind.
- Repair any rotted window trim.
- Remove redundant fire escape on the fourth floor east side.
- Remove pipe rail handrail at front steps and install new wrought iron handrail and garden surround.
- Repair front garden granite curb surround.
- Install front path lighting to the main entrance stairs.
- Plant a new tree centrally in the front garden, either a flowering magnolia or a Japanese Maple.
- Install tree up-lights
- Re-paint and re-certify all fire escapes.
- Remove wooden stairs from the rear of the building to the alley level and replace with new masonry stairs and wrought iron railing to match the Marlborough Street façade.








North Façade existing









South Façade existing



South Façade proposed




Front Door



Damaged brownstone



Front stair detail



Damaged brownstone and efflorescence





Front bay window

Bay window brownstone base





Front Door

Front steps and railings







Front entrance staining and damage detail




Front Door detail



Front Door detail



Bay window detail




Third floor window with staining




Curb detail



Stair detail




3rd, 4th and 5th floor windows





3rd, 4th and 5th floor windows





East Façade on 5th Floor





West Façade on 5th Floor












Brown stone and brick damage and staining detail






Brick efflorescence and staining








Mansard window detail










Rear facade detail





Rear Yard existing






Public Alley

Rear Yard proposed



Existing Hedge



Proposed Hedge and Rail






Jane Magnolia
Proposed Central Tree

Japanese Maple





Wrought iron railing and garden fence. Example at 245 Marlborough Street

Landscape Lighting