


116 CHANDLER ST

BOSTON, MA

FRONT ENTRY MODIFICATION



EMBARC



116 CHANDLER



118 CHANDLER





NEW BRACKETS, APPLIED
PANELS, KEYSONE AND
ROOF TO MATCH 118
CHANDLER

REFURBISH DOORS AND
TRANSOM PER PREVIOUS
APPLICAITON

PATCH, REPAIR AND
PAINT EXISTING PANELED
ENTRY AND TRIM



1

CHANDLER STREET FRONT ENTRY ELEVATION - EXISTING

1/2" = 1'-0"

2

CHANDLER STREET FRONT ENTRY ELEVATION - PROPOSED

1/2" = 1'-0"

Black
2132-10

PAINT COLOR



EXTERIOR LIGHT - RESTORATION HARDWARE CHEVALIER SCONCE IN BRONZE