




City of Boston Public Facilities Department  
Finegold Alexander Architects

**McKim Building Courtyard Fountain**  
Boston Public Library, Boston, MA  
May 26, 2020





Existing Tile Photos



Proposed Replacement Tile

Flush mounted light fixture, typ at (4) locations. Lighting layout and quantities to match existing


Replace filter inlet fittings. Typ. at 4 locations

Reinstall existing vertical stone pavers at surround in same locations as existing



Main drain grate


Concrete slab poured in place, sloped for drainage. Concrete slab thickness at edges of basin to match existing to accommodate for reinstallation of vertical pavers. Provide waterproofing and mosaic tile

Reinstall pedestal at same location as existing



2 Basin Construction Plan  
1/4" = 1'-0"

| Construction Plan Legend  |   |
|---|---|
|  | Marble Mosaic Tile & Concrete replacement at upper slab |
|  | Existing Stone & Pavers to remain                       |



1 Basin Section  
1/2" = 1'-0"



Existing Fountain



Proposed Fountain Design

