
Improvements to the Hamilton, Glover, and Sarmiento statue nodes

Landmarks Commission Hearing | 3.23.2021









PROJECT TEAM

Friends of the Public Garden

Bob Mulcahy Director of Parks Care & Capital Projects bob@friendsofthepublicgarden.org 617-723-8144 x206

Margaret Pokorny Friends Member & Project Champion

Available Light

Steven Rosen, President & Creative Director Hess Smith, Associate IALD

Lentine Electric Service

John Lentine, President

Boston Parks & Recreation

Liza Meyer, Chief Landscape Architect Rob Rottenbucher, Chief Engineer


Weston & Sampson

Gene Bolinger, RLA, Principal Cassie Bethoney, RLA, Project Manager Lanie Cohen, Site Designer Dan Marchand, Electrical Engineer

Fleming Brothers (site contractor) John Fleming, Owner


















EXISTING SITE CONDITIONS: HAMILTON













BASIC IMPROVEMENT PROGRAM: HAMILTON




- Statue uplighting and incidental electrical work
- Walkway repaving
- Redesign of curbing
- Site restoration
- Protection of existing trees







PROPOSED IMPROVEMENTS: HAMILTON





PROPOSED PAVING DETAIL: HAMILTON














Curbs to match look of the new beveled curb at Collins statue





LIGHTING FIXTURE PLAN: HAMILTON








LIGHTING FIXTURE PLAN: HAMILTON







LIGHTING FIXTURE PLAN: HAMILTON



This Drawing Shows Design Intent Only And Is Not To Be Used As A Construction Document






EXISTING SITE CONDITIONS: GLOVER















BASIC IMPROVEMENT PROGRAM: GLOVER




- Statue uplighting and incidental electrical work
- Treatment of set cobbles
- Curb replacement
- Walkway repaving
- Site restoration
- Protection of existing trees






PROPOSED SITE IMPROVEMENTS: GLOVER





LIGHTING FIXTURE PLAN: GLOVER








LIGHTING FIXTURE PLAN: GLOVER








LIGHTING FIXTURE PLAN: GLOVER









This Drawing Shows Design Intent Only And Is Not To Be Used As A Construction Document






EXISTING SITE CONDITIONS: GARRISON








PROPOSED SITE IMPROVEMENTS: GARRISON







EXISTING SITE CONDITIONS: SARMIENTO







YEW REMOVED WINTER 2020

YEW REMOVED WINTER 2020



BASIC IMPROVEMENT PROGRAM: SARMIENTO



- Statue uplighting and incidental electrical work
- Planting improvements
- Additional curbing to accommodate uplighting placement
- Site restoration
- Protection of existing trees





PROPOSED SITE IMPROVEMENTS: SARMIENTO


EXISTING TREE, TYPICAL EXISTING RELOCATED PLAQUE **EXISTING CONCRETE PATHWAY TO REMAIN** NEW PLANTING TO ACCOMMODATE EX. **EXISTING BITUMINOUS CONCRETE TO REMAIN** AZALEA TO REMAIN **PROPOSED GRANITE UNIT PAVERS** PROPOSED ELECTRICAL HANDHOLE DOMINGO FAUSTINO SARMIENTO MONUMENT PROPOSED LIGHTING CABINET **EXISTING GRANITE CURB TO REMAIN EXISTING IRRIGATION CABINET**



SCALE: 1" = 4'-0




PROPOSED SECTIONS: SARMIENTO



B



LIGHTING FIXTURE PLAN: SARMIENTO



LIGHTING FIXTURE PLAN: SARMIENTO







PROPOSED LIGHTING CABINET AT ALL STATUES



To Match Look of the New Cabinet at previous lighting improvement projects





Questions? Thank you!

B

