# BACK BAY ARCHITECTURAL COMMISSION DESIGN REVIEW APPLICATION

ROOF DECK REPLACEMENT 362 COMMONWEALTH AVE


Diego Arabbo, P.E.

Senior Project Manager

10/03/2022




THE EXISTING COMMON ROOF DECK WAS REMOVED IN 2020-2021 TO RE-ROOF THE BUILDING. THIS DESIGN REVIEW APPLICATION IS FOR A NEW COMMON DECK SGH TO REPLACE THE ONE THAT WAS REMOVED.




#### **EXISTING COMMON DECK THAT WAS REMOVED TO RE-ROOF**










(facing south)



(facing east)

## PORTIONS OF THE RAILING FOR THE EXISTING COMMON DECK THAT WAS REMOVED WERE VISIBLE FROM COMMONWEALTH AVE.






Google street view, 2020


### **CURRENT CONDITIONS (PLAN)**





### **CURRENT CONDITIONS (SECTION)**






09/16/22



# HISTORICAL BACKGROUND

#### 1981 - PLANS FOR THEN NEW PENTHOUSE UNITS SHOW A COMMON DECK






### 1998 - THE CITY OF BOSTON ISSUED A PERMIT FOR THE REPLACEMENT OF THE ROOF DECK



CITY OF BOSTON — INSPECTIONAL SERVICES DEPARTMENT.		
The Edition of Deliving Services Deliving Ment		
SPECIAL FORM APPLICATION No		
Demolition, Ordinary Repairs and Minor Alterations Not Involving Vital Structural Changes.		
Structural Changes.  This form NOT TO BE USED for ADDITIONS or CHANGES OF OCCUPANCY.		
The undersigned hereby applies to the Commissioner, Inspectional Services		
for a permit to perform the work described herein:		
DATE4/28/98		
DATE 4/28/98 Street and No. 362-366 COMMONWEALTH AVE Historic District/Ward5		
Name of Owner COMM., AVE REALTY TRUST Address 1462 COMMONWEALTH AVE		
Material of Building BRICK Group Occupancy and Division		
Size of building, feet front90 feet rear90; feet deep110; No. of stories7.		
How is building NOW occupied? 59. APTS, . TWO . OFFICES, . LAUNDROMAT, . FOUR, STORES, .		
Check all means of egress from this building: ATM MACHINE DOC# 4237/97		
Main stairs Back stairs Fire escapes Con. balconies Any other		
Is this work being done to remove Building Code Violations? Yes		
Detail of proposed work — STATE EXACTLY WHAT IS TO BE DONE:		
REPLACE EXISTING DECK ON ROOF, BEACUSE OF DAMAGED WOOD, EXISTING SIZE		
TO STAY SAME SWEAR THAT THIS APPLICATION AND PLANS CONFORM TO THE ISSUED CERTIFICATE OF		
CONFORM TO THE ISSUED CERTIFICATE CO. 1319 BB. APPROPRIATE SESSIDESIGN APPROVAL Chack		
ON EXEMPTION/NON-APPLICABILITY GIB		
OR NO EXTERIOR WORK IS INVOLVED		
6/34/58 Estimated Cost, \$ 10,000		
Ingrates set forth in this apprincation and the same or the same of the same o		
under penalty of perjury. The applicant also attests that he has read the statement printed on the reverse side and abides by its requirements.		
Address 1462 COMMONWEALTH AVE BOSTON		
( Signature of Owner of Authorized Agent) Phone		
Ungo & The soule		
(Signature of Licensed Builder or Wrecker) (Name of Contractor)		
Address SAME Address & PROSPECT COPPET		
Lic. No. 039828 . Class		
My license expires		
4		
Ry		
Бу		




## 2002 - APPLICATION SUBMITTED TO THE CITY OF BOSTON FOR THE REPLACEMENT OF THE ROOF DECK



• • • •		
CITY OF BOSTON — INSPECTIONAL SERVIC 1010 Massachusetts Avenue, Boston,	MA 02118	
SPECIAL FORM APPLICATION No	ot Involving Vital	
tructural Changes. his form NOT TO BE USED for ADDITIONS or CHANCE. The undersigned hereby applies to the Commissioner, In or a permit to perform the work described herein:	S OF OCCUPANCY 8 A 9	
DATE7-29-02	#849	
treet and No. 362-366 COMMONWEALTH AVENUE	Historic District/Ward 5	
Name of Owner .362 . COMMONWEALTH . AVE . CONDO	. AddressSAME	
ASSQC,Zc	one Fire Limit	
Material of Building BRICK Size of building, feet front; feet rear	; feet deep; No. of stories	
10 50 APTS 2 ODFICES, LAUNDRAMAT, 4 510556		
Pack stairs Fire escapes Con, Dalconles Any of the		
sthis work being done to remove Building Code Violations? Yes		
Detail of proposed work — STATE EXACTLY WHAT IS TO BE DONE:		
PRMOUF AND REPLACES THREE EXISTING ROOF, DECKS. FURNISH AND		
INSTALL NEW EPDM ROOFING OVER POLYISOCYANURATE INSULATION.  REINSTALL ROOF DECKS TO ORIGINAL CONFIGURATION. REMOVE AND REINSTALL		
REINSTALL ROOF DECKS TO ORIGINAL CONTAND REGLAZE TWO ELEVATOR PENTHOUSE SI	KYLIGHTS & TWO STAIRWELL	
SKYLIGHTS. REROUF FOUR BAY WINDOWS:		
SKINIONIE ADROCE		
	Estimated Cost, \$ 118,675	
The facts set forth in this application and in the accounder penalty of perjuty. The applicant also attests the	and he has read the statement printed on the reverse	
side and abides by its requirements.	131 PARK DR BOSTON	
( n)	Address 617-236-6977 02215	
(Signature of Authorized Agent)	Phone	
(Signature of Proonsed Duilder or Wrecker)	PROGRESSIVE .ROOFING(Name of Contractor)	
Address GAMALOT . DR BOXFORD	Address 940 EASTERN AVENUE	
Lic. No. 37814 Class CS	MALDEN; MA 02148	
	Phone 781–324–0178	
Approved (date)	Permit granted	
D. Wan	Ву	

### COMMERCIALLY-AVAILABLE AERIAL IMAGERY SHOWS THE COMMON DECK CONTINUOUSLY BETWEEN 2002 AND 2020





2009 SGH



12








# EXISTING CONDITIONS PHOTOS

### VIEW OF PROPERTY FROM MASS AVE (FACING NORTHEAST)






### VIEW OF PROPERTY FROM COMMONWEALTH AVE (FACING SOUTHEAST)







### VIEW OF PROPERTY FROM COMMONWEALTH AVE (FACING SOUTHWEST) SGH



### VIEW OF PROPERTY FROM PUBLIC ALLEY 430 (FACING NORTHWEST)









## EXISTING ROOF CONDITIONS (FACING NORTH)












# PROPOSED COMMON DECK





#### PROPOSED (SECTION)















### STREET PHOTO WITH NEW RAILING





### STREET PHOTO WITH NEW RAILING



