



WINDOWS
&
DOORS

18 Concord Square

Presented By:

Pella Windows and Doors



WINDOWS
&
DOORS

Existing Conditions





WINDOWS
&
DOORS

Existing Conditions





WINDOWS
&
DOORS

Existing Conditions

- Not Visible from Public Way
- Egress Well
- Non-Original
- Wood Windows
- Metal Tracks
- Severely rotted sills
- One over One



WINDOWS
&
DOORS

Proposed

- Fiberglass Windows
- Non Porous Material
- Resilient
- Two over Two
- White
- Grilles Between Glass



WINDOWS
&
DOORS

Questions



Any Questions?