



94 Beacon Street - View of Roof
February 28, 2019



94 Beacon Street Dormer Trim Detail
2-28-19



94 Beacon Street View of Dormer
2-28-19



94 Beacon Street View of Dormer Trim
2-28-19

RED HATCHED AREA DENOTES AREA OF ROOF TO BE REPLACED WITH SALVAGED SLATE ROOF & NEW SLATE TO MATCH EXISTING, TYP.

NEW COPPER FLASHING @ GLAZED ROOF PERIMETER, TYP.

NEW COPPER GUTTER & FLASHING

GLAZED ROOF SYSTEM TO MATCH EXISTING ROOF PITCH. ALL EXTERIOR MULLION AND SOLID PANELS TO BE COPPER CLAD

